Karnataka Fire and Emergency Services Department

Office of the District fire officer,

Peenya Fire Station Peenya, Bengaluru – 560058. Ph No.080 – 22971533.



No.27/FSR/DFO/PFS/2024.

01-06-2024.

To,

The Authorized Signatory, M/s.Gopalan Foundation® No.5, Richmond Road Bengaluru-560025

Sir,

<u>Sub:</u> Issue of Fire safety recommendation to M/s.M/s.Gopalan Foundation® situated at No.79, Kondashettihalli Road, Mavallipura, Hesaraghatta Hobli, Bengaluru-560089.

Ref: Your letter dated:28-05-2024.

ANNEXURE-B

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory)

With reference to the subject above cited, the premises *M/s.Gopalan Foundation*® situated at *No.79*, *Kondashettihalli Road*, *Mavallipura*, *Hesaraghatta Hobli*, *Bengaluru-560089* was inspected by the Fire Station Officer, Peenya Fire Station on 29-05-2024 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the premises and the details as under:-

A. Details of the building / premises :-

01	Name and Address of the	:	The Authorized Signatory
	Applicant.		M/s. Gopalan Foundation®
		-	No.5, Richmond Road
1		>	Bengaluru-560025.
02	Name and Address of the	:	M/s.Gopalan Foundation®
	premises.		No.79, Kondashettihalli Road, Mavallipura,
-			Hesaraghatta Hobli, Bengaluru-560089 District
			The district

03	Name and address of the Building owner	:	Secretary M/s. Gopalan Foundation® No.79, Kondashettihalli Road, Mavallipura, Hesaraghatta Hobli, Bengaluru-560089.				
04	Number of buildings	:	01 Building Only.				
04	Number of buildings						
05	Number of floors	:	Ground & an upper floor.				
06	Floor-wise details of occupan	Floor-wise details of occupancy:-					
	Ground floor		12 Class Rooms, Office & Library.				
	1 st floor	:	Class Rooms, Chemistry, Biology, Physics. Computer Labs & Seminar Hall.				
07	Height of the building	:	06.60 Mtrs.				
08	Site area	:	40164.00 Sq.Mtrs.				
09. Built-up area of each floor:-							
	Ground floor	:	4182.01 Sq.Mtrs.				
	1 st floor	:	4182.01 Sq.Mtrs.				
10.	Total built-up area	:	8364.02 Sq.Mtrs.				
11.	Surrounding properties:-						
	North (Front)	:	School Property.				
	South (Rear)	:	Private Property.				
	East (Side)	:	Private Property.				
	West (Side)	:	Government Nala & Private property.				
12.	Set-back area available around the building :-						
	North (Front)	:	06.00 Mtrs.				
	South (Rear)	:	06.00 Mtrs.				
	East (Side)	:	06.00 Mtrs.				
	West (Side)	:	06.00 Mtrs.				
	Allowed setbacks (Open space) Should be maintained free from further obstruction/construction						

B. On inspection of this School/Collage premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-

SI.	Details	Existing
No.(1)	(02)	(03)

Recommends



1.	Accessibility to the premises	The site is ac 09.00 mts Kondashettihalli connected to main road locate side & its hard the weight of 45.	rs wide road which is Hesaraghatta ed on northern ened to carry	
2.	No. of entrances	01 entrance of width have been	` 06.00 Mtrs provided.	Adequate.
3.	Diesel Generators	Not Pro	vided.	A generator of suitable KVA capacities is available to supply alternate power to all the emergency provision of the building.
4.	Number of staircases available	Nos. of staircases Width of staircases Width of treads Height of risers Nos. of riser per flight Height of handrails	: 03 No's. : 1.30 mtrs : 30 Cms : 15 Cms. : 10 No's : 01.00 Mtrs.	Complied.
5.	Portable Fire extinguisher	05 ABC fire each of 04 kgs DCP fire extingu 04 kgs capacity extinguishers eacapacity have be	capacity, 07 hishers each of & 02 Co2 fire ch of 4.5 kgs	A. One water mist extinguisher of 9 ltrs capacity should kept near each staircase landing. B. One mechanical foam extinguisher of 9 ltrs capacity & One ABC type extinguisher of 06 kgs capacity should be provided near diesel generator. C. One CO2 type fire extinguisher, of 4.5 kgs capacity should be provided near each electrical partie listed & electrical partie listed

	and the same of th	THE RELEASE OF THE PARTY SERVICE AND THE PROPERTY OF THE PARTY SERVICES AND THE PARTY SERVICES.	D. One ABC type fine
			extinguisher of 06 kgs
	, N 1		capacity should be
			provided for every 100
	3,1		Sq Mtrs should be
	1		provided.
6	First aid Hose	Not provided.	Hose reel hose system
6,	reel hose.	rvot providees.	shall be provided near the
	reer moser		staircase. (One Hose reel
			hose system for every
			1000 Sq. mtrs) the hose
			reel hose of minimum 19
			mm size and of 30.00
			mtrs length to reach the
			farthest point of each floor
			should be provide with a
			shut off branch having a
			nozzle of 5 mm size. The
			hose reel hose should be
			connected at each landing
			by means of an adaptor.
7.	Terrace tank	Not provided.	The system should be connected to an over head
	over		tank of 10,000 ltrs
	respective tower terrace.		capacity. Further if
	tower terrace.		basement As provided the
	is the second second		tank capacity shall be
			increased to 5,000 ltrs
			capacity. (The water tank
			should be kept
			exclusively for
			firefighting)
8.	At the terrace	Not provided.	The system should be
	tank level		connected to an Booster
	with		pump capable of
	minimum		delivering 450 LPM or of
	pressure of		5 HP capacity at each block.
	3.5 kg/cm ² .	P	Further the system
			should be connected to
			an alternative source of
			power supply.
,			of the District

					13
14	(13.	12.	Ξ	10.	.9
Fire fighting training	Nominate one fire Nodal officer	Fire order (Fire safety plans)	Fire siren	No smoking board	Escape route
Not trained.	The school authority has been nominated Mr. Veerabhadraiah a fire nodal officer	Not provided.	Not provided.	Not provided.	Not provided.
At least 40% of Teaching and non teaching staff should be got trained basic fire fighting at R.A. Mundkur Fire and Emergency Academy, Bray Tughatta road, Bengalur 1990, 20020	Complied.	A notice board indicating the details of actions to be taken in case of emergency should be displayed near each staircase landings with the telephone numbers of our Peenya Fire Station 080-22971545, CFCR No's-080-22971500/550/600 or 101 or 112, and telephone numbers of nearest Ambulance Service	A fire siren shall be installed in the premises to inform the inmates in the case of a fire emergency and evacuate the area.	COTPA Sec-4 direction No smoking area, Smoking is an offence board should be written in English and kannada both language shall be prominently displayed at inside the entry/exit of each floor.	Direction in which the students have to move in the event of an emergency should be displayed in the corridor on each floor during evacuation.



- Fire precautionary measures:-A.Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory
- B. Accumulation of combustible waste in and around the premises should be avoided.
- C. The exit ways shall be always kept clear without any obstruction.
- D.Liquefied petroleum gas should not be stored in the building.
- E. The doors shall not be kept locked / latched during working hours and shall be free
- Ή. During the class hours the class room doors shall not be locked from inside to from obstruction.
- G.As per Hon'ble supreme court order all teachers and staffs shall be trained to handle outside. safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordinate with fire service department.

Department is of the above recommendations in column-4 of serial-B within 3 months and Hesaraghatta Hobli, Bengaluru-560089 subject to condition and compliance Foundation® compliance to the undersigned. Under the above circumstance the Karnataka Fire &situated issuing 'Fire Safety at No. 79, Kondashettihalli Road, Recommendation ' **Emergency Service** for Mavallipura, M/s. Gopalan

year from the date of issue This 'Fire Safety Recommendation' is issued for a period of only one

Code- 2016 Part-4 clause 3.1.3 complied with mandatorily. All requirements recommended above are of Fire and Life as safety will have per **National Building** to be

Yours faithfully

Karnataka Fire & Emergency Services District Fire Officer 116124

Peenya Fire Station, Bengalury-560 058